



# NORTHERN PIPE, INC.

CLEAN - INSPECT - REPAIR

1772 South Vandenberg Road  
 Green Bay, Wisconsin 54311  
 (920) 468-7074  
 www.northernpipeinc.com

Measured from MH	Tap Location	Size	Material	Lateral Seg. Ref.	City
Upstream	248.1	4	Vitrified Clay Pipe	109 W. Bradley Rd	Village of Fox Point
Surveyed By	Certificate Number	Building Address	Street	Upstream MH	Downstream MH
Avery DeJardin	U-108-6266	109	W Bradley Rd	04-069	04-068
Direction	Purpose	Weather	Date	Time	Length Surveyed
Upstream	Maintenance Related	Light Rain	20180122	5:00 PM	5.8
<b>Additional Information</b>					
95' to house					

Ftg.	Code	Description	Pct.	Position	Cont.	Comment
0.0	AML	Access Point - Mainline				Start of inspection at Mainline (Tap, Factory Made Connection)
0.0	MWL	Water Level	10			
0.6	RFJ	Roots, Fine: Joint		7 to 5		
1.5	RBJ	Roots, Ball, Joint	90	7 to 5		
3.6	RBJ	Roots, Ball, Joint	95	7 to 5		
5.8	MSA	Survey Abandoned				

Camera will not pass heavy roots in lateral.  
 End Report



# NORTHERN PIPE, INC.

CLEAN - INSPECT - REPAIR

1772 South Vandenberg Road

Green Bay, Wisconsin 54311

(920) 468-7074

www.northernpipeinc.com

Measured from MH	Tap Location	Size	Material	Lateral Seg. Ref.	City
	248.1	4	Vitrified Clay Pipe	109 W. Bradley Rd	Village of Fox Point
Surveyed By	Certificate Number	Building Address	Street	Upstream MH	Downstream MH
Avery DeJardin (NPI)	U-108-6266	109	W Bradley Rd	04-069	04-068
Direction	Purpose	Weather	Date	Time	Length Surveyed
Upstream	Maintenance Related	Light Rain	20180122	5:00 PM	5.8

### Additional Information

95' to house



RBJ - Roots, Ball, Joint @ 1.5 ft.



RBJ - Roots, Ball, Joint @ 3.6 ft.