Connie file Start file Thanks

### Carl W. Backus Attorney at Law 5900 N. Port Washington, Rd. #206 Milwaukee, Wisconsin 53217

(414) 332-2880

September 24, 1991

Mr. Michael K. Lynett Fox Point Engineer 7200 North Santa Monica Blvd. Milwaukee, Wisconsin 53217

**RE:** Patrick Media-Fox

Dear Mike:

This is to follow up the occasion where you, Noreen, and I met with Mr. Fox and representatives of Patrick Media on September 4, 1991. We walked the area and discussed various theories of why the water was accumulating in front of the berm and how to remove the water. Mr. Fox indicated that he had no objection to having the water run through his backyard if a pipe or culvert were put through the berm.

These are the tentative conclusions I believe we came to.

1. Although Patrick Media had surveys with some elevations, they agreed to obtain further elevations for your review.

2. After you receive the elevations, you would try to determine the source of the water that is gathering in front of the berm.

3. Thereafter, you would make cost estimates of the various possible solutions as you see them.

After we had this meeting, I talked to Mr. Fox briefly and he did indicate that he would be willing to talk about the costs of any solution.

Very truly yours,

Carl W. Backus

CWB:mb

cc: Noreen Cook

# Carl W. Backus

Attorney at Law 5900 N. Port Washington, Rd. #206 Milwaukee, Wisconsin 53217

## (414) 332-2880

September 24, 1991

Mr. Michael K. Lynett Fox Point Engineer 7200 North Santa Monica Blvd. Milwaukee, Wisconsin 53217

RE: Patrick Media-Fox

Dear Mike:

This is to follow up the occasion where you, Noreen, and I met with Mr. Fox and representatives of Patrick Media on September 4, 1991. We walked the area and discussed various theories of why the water was accumulating in front of the berm and how to remove the water. Mr. Fox indicated that he had no objection to having the water run through his backyard if a pipe or culvert were put through the berm.

These are the tentative conclusions I believe we came to.

Although Patrick Media had surveys with some elevations, they agreed to obtain further elevations for your review.

After you receive the elevations, you would try to determine the source of the water that is gathering in front of

Thereafter, you would make cost estimates of the the berm.

various possible solutions as you see them.

After we had this meeting, I talked to Mr. Fox briefly and he did indicate that he would be willing to talk about the costs

of any solution.

Very truly yours,

Carl W. Backus

CWB:mb

cc: Noreen Cook

#### VILLAGE OF FOX POINT

MILWAUKEE COUNTY

WISCONSIN



VILLAGE HALL 7200 N. SANTA MONICA BLVD. FOX POINT 53217-3505 414-351-8900

September 1, 1998

 A second sec second sec

Mr. Dan Pomeroy Real Estate Manager Eller Media Company Nll W24600 Silvernail Road Pewaukee, Wisconsin 53072-5599

Dear Mr. Pomeroy:

We have inspected your premises and found:

1\_\_\_\_\_

Elm tree(s) infected with Dutch Elm Disease; please remove same.

Elm logs or firewood stored in yard.

The above should be removed within ten (10) days from date hereof in accordance with Village Ordinances Numbers 250 and 299. The Department of Forestry requests such removal as a control measure against the spread of Dutch Elm Disease. May we have your cooperation? For further information, please call 351-8900. Thank you.

Sincerely,

Judy Shirley Village Forester

Dated: <u>September</u> 1, 1998

Location: tree is located south of billboard near road; in wooded, shrubby area; tree marked with red "x".

8500 Block N Port Rd - East side south of Bergon

#### Carl W. Backus

#### Attorney at Law 5900 N. Port Washington, Rd. #206 Milwaukee, Wisconsin 53217

#### (414) 332-2880

September 24, 1991

Mr. Michael K. Lynett Fox Point Engineer 7200 North Santa Monica Blvd. Milwaukee, Wisconsin 53217

**RE:** Patrick Media-Fox

Dear Mike:

This is to follow up the occasion where you, Noreen, and I met with Mr. Fox and representatives of Patrick Media on September 4, 1991. We walked the area and discussed various theories of why the water was accumulating in front of the berm and how to remove the water. Mr. Fox indicated that he had no objection to having the water run through his backyard if a pipe or culvert were put through the berm.

These are the tentative conclusions I believe we came to.

1. Although Patrick Media had surveys with some elevations, they agreed to obtain further elevations for your review.

2. After you receive the elevations, you would try to determine the source of the water that is gathering in front of the berm.

3. Thereafter, you would make cost estimates of the various possible solutions as you see them.

After we had this meeting, I talked to Mr. Fox briefly and he did indicate that he would be willing to talk about the costs of any solution.

Very truly yours,

Carl W. Backus

CWB:mb

cc: Noreen Cook