




NORTHERN PIPE, INC.

CLEAN - INSPECT - REPAIR

1772 South Vandenberg Road
 Green Bay, Wisconsin 54311
 (920) 468-7074
 www.northernpipeinc.com

| | | | | | |
|------------------|---------------------|------------------|---------------------|-------------------|----------------------|
| Measured from MH | Tap Location | Size | Material | Lateral Seg. Ref. | City |
| Downstream | 118.8 | 4 | Vitrified Clay Pipe | 101 E. Bradley Rd | Village of Fox Point |
| Surveyed By | Certificate Number | Building Address | Street | Upstream MH | Downstream MH |
| Avery DeJardin | U-108-6266 | 101 | E Bradley Rd | 04-068 | 04-067 |
| Direction | Purpose | Weather | Date | Time | Length Surveyed |
| Upstream | Maintenance Related | Light Rain | 20180122 | 5:11 PM | 100.7 |

Additional Information





NORTHERN PIPE, INC.

CLEAN - INSPECT - REPAIR

1772 South Vandenberg Road
Green Bay, Wisconsin 54311
(920) 468-7074
www.northernpipeinc.com

| | | | | | |
|-------------------------|---------------------|------------------|---------------------|-------------------|----------------------|
| Measured from MH | Tap Location | Size | Material | Lateral Seg. Ref. | City |
| | 118.8 | 4 | Vitrified Clay Pipe | 101 E. Bradley Rd | Village of Fox Point |
| Surveyed By | Certificate Number | Building Address | Street | Upstream MH | Downstream MH |
| Avery DeJardin (NPI) | U-108-6266 | 101 | E Bradley Rd | 04-069 | 04-068 |
| Direction | Purpose | Weather | Date | Time | Length Surveyed |
| Upstream | Maintenance Related | Light Rain | 20180122 | 5:11 PM | 100.7 |

Additional Information



RMB - Roots, Medium: Barrel @ 0.0 ft.