

**Tabular Report of Lateral**      102 W. Willow Rd.      for    Village of Fox Point  
**Main Line**                              MH 09-028 to 09-027  
**Project**                                      20341

<b>Job Number</b>	<b>Work Order</b>		<b>Media #</b> 20341	<b>Setup</b> 215
<b>Surveyor</b> Bill Krohn	<b>Certificate #</b> U609-1885		<b>Cert#</b> 07/29/2020	1:50:00 PM
<b>Street</b> Easement between Seneca and Navajo	<b>City</b> Fox Point			
<b>UpManhole</b> MH 09-028	<b>Downstream MH</b> MH 09-027			
<b>Drainage</b>	<b>Clean Out</b>		<b>Building Address</b>	
<b>System Owner</b> Village of Fox Point	<b>Size</b> 6 ins	<b>Total Length</b>	<b>Ft</b>	<b>Property Line</b> 0 Ft
<b>Direction</b> U	<b>Material</b> Polyvinyl Chloride	<b>Lining</b>		
<b>Use</b> Sanitary	<b>PreCleaned</b> No Pre-Cleaning	<b>Weather</b> Dry		
<b>Location</b> Easement/Right of Way	<b>Date Cleaned</b>	<b>Cleanout RimToInvert</b>		0 Ft
<b>Year Laid</b>	<b>TapLoc</b> 0 Ft	<b>Survey Purpose</b> Routine Assessment		
<b>Comments</b> 8" lined main line			<b>Start MH</b> Upstream	
<b>Location Comments</b> Easement Between Seneca Rd. and Navajo Rd.			<b>Length Surveyed</b>	19.9 Ft
<b>Northing</b>	<b>Easting</b>	<b>Elevation</b>		
<b>Coordinate System</b>	<b>GPS Accuracy</b>			

Count	Video	CD Code	In1	In2	%	Jnt	Fr	To	ImRef	Remarks
0.0		ST								Start of Survey
0.0		AML								Mainline
0.0		MWL			5					Water Level
3.9		LLD			50					Alignment Left Down
5.2		LR			25					Alignment Right
7.5		LRU			25					Alignment Right Up
8.5		MMC								Material change
19.9		MSA								Abandoned Survey

19.9 Ft    **Total Length Surveyed**

**CustomFields**

**Notes**

Lateral is a tap tee to top / 278.8' from MH 01-028

Televising 12' beyond top of riser



**Great Lakes TV Seal, Inc.**  
**Phone:920-863-3663**  
**Fax:920-863-3662**