Tabular Report of Lateral 1000 E. Bradley Rd. for Village of Fox Point

MH 04-047 to 04-048 **Main Line**

Project 20341

Work Order Job Number Media # 20341 Setup 127 Surveyor Bill Krohn Certificate # U609-1885 Cert# 07/14/2020 9:18:00 AM Street E. Bradley Rd. City Fox Point **UpManhole** MH 04-048 Downstream MH MH 04-047 Drainage Clean Out **Building Address System Owner** Ft **Property Line** 0 **Ft** Village of Fox Point Size 6 **ins Total Length** Direction U Material Polyvinyl Chloride Lining No Pre-Cleaning Use Sanitary **PreCleaned** Weather Dry Location Light Highway **Date Cleaned** Cleanout RimToInvert 0 **Ft** Year Laid 0 **Ft**

TapLoc Survey Purpose Routine Assessment Comments 21" main line

Location Comments Length Surveyed 20.6 Ft

Northing Easting Elevation **Coordinate System GPS Accuracy**

Count Video	CD Code		ln1	ln2	%	Jnt	Fr	То	ImRef	Remarks
0.0	ST	Start of Survey								
0.0	AML	Mainline								
0.0	MWL	Water Level			5					
4.2	LD	Alignment Down			50					
6.8	MMC	Material change								TO VCP
8.8	FC	Fracture Circumferential				J	12	05		
11.7	FC	Fracture Circumferential				J	12	12		
17.3	FM	Fracture Multiple				J	12	06		
20.6	FM	Fracture Multiple				J	12	12		
20.6	MSA	Abandoned Survey								DISCONTINUE TELEVISING

20.6 **Ft Total Length Surveyed**

CustomFields

Notes

Lateral is a tap tee to top / 124' from MH 04-047

Televising 12' beyond top of riser



Start MH

Downstream